

AMEREC STEAM KT60/K60 CONTROL ERROR CODES

The control may display an error code if the steam generator is not functioning properly.

CODE	PROBABLE CAUSE
E001	OPEN TEMP SENSOR CONNECTION
E002	SHORTED TEMP SENSOR CONNECTION
E003	CONTROL COMPATIBILITY ISSUE (NEW CONTROL W/OLD PCA)
E007	OPEN WARM START TEMP SENSOR CONNECTION
E008	SHORTED WARM START TEMP SENSOR CONNECTION
E044	OVERHEATED WARM START TEMP SENSOR (OVER 225 DEG. F.)
E055	OVERHEATED ROOM TEMP SENSOR (OVER 130 DEG. F.)